

<https://www.telephonecollectors.info/>

TEST NOTES:



1. ADJACENT RELAYS SHALL NOT BE ENERGIZED. SEE BSP.



EQUIPMENT NOTES:

201. 48B2 LAMPS ARE OF A.E. CO. MANUFACTURE. THEY MAY BE USED INTERCHANGEABLY WITH 2Y LAMPS AND ARE SHOWN ONLY FOR MAINTENANCE PURPOSES WHEN THIS CIRCUIT IS USED IN 35-E-97 OFFICES.

DWG	ISS
158	158
160	160
178	178
180	180
190	190



210 55315-02

LINE FINDER CONTROL CKT.
BELL TELEPHONE LABORATORIES INC.

3 SHEETS, SHEET 3
SD-31922-013
R PRINTED IN U.S.A.