PBX SYSTEMS
NO. 550B, 550C, 550SC, 551A,
551B, 551D, 552A, 552B, 552D,
552E, 555, 556A, 605A, 606B,
607A, 607B, 0R 608A
MANUAL CONFERENCE CIRCUIT
WITH VOICE REPEATER
ARRANGED FOR A MAXIMUM OF
4 OR 5 SIMULTANEOUS CONNECTIONS

CHANGES

B. Changes in Apparatus

B.l Superseded

Superseded By

601Al loading coil case for ${\tt C3}$ loading coil in Fig. 1, option M.

601B1 loading coil case, option B.

D. Description of Changes

 ${\tt D.1}$ $\,$ Options C and D were designated for F and R resistors to correct an error.

F. Changes in CD Sections

F.1 In B.2 and D.2 of Section IV, "Resistor (T)" should read "Resistor (R)."

BELL TELEPHONE LABORATORIES, INCORPORATED

DEPT 5336-WAJ-FNR