

DIAGNOSTIC LOADING PROCEDURE
NO. 1A AUTOMATIC MESSAGE ACCOUNTING
RECORDING CENTER (AMARC) GENERIC 3

1. GENERAL

1.001 This addendum supplements Section 201-900-331, Issue 1. Place this pink sheet ahead of Page 1 of the section.

1.002 This addendum is issued to correct the TP numbers for the stand alone (SA) copy

(SACOPY) program and diagnostic data tapes. This addendum does not affect the Equipment Test List.

2. CHANGES TO SECTION

2.001 On Page 3, paragraph 2.01, change SACOPY data tape (TP-5P355-04) to SACOPY diagnostic data tape (TP-5P355-02).

NOTICE

Not for use or disclosure outside the
Bell System except under written agreement

Printed in U.S.A.