

FD-2240A
6.3MB OPTICAL LINE TERMINATING MULTIPLEXER
SPARE UNITS AND COMPONENTS

1. GENERAL

- 1.01 This section is a cover sheet for the NEC America, Inc., FD-2240A 6.3MB Optical Line Terminating Multiplexer Spare Units and Components. This section is reproduced with permission of NEC America, Inc., and is equivalent to NEC practice NECA 365-407-503, Issue 2.
- 1.02 Whenever this section is reissued the reason(s) for reissue will be listed in this paragraph.
- 1.03 This section provides a listing of spare units and components necessary to support for the FD-2240A 6.3MB Optical Line Terminating Multiplexer(6.3MB O-LTM).
- 1.04 If corrections are required in the attached document, use Form-3973 as described in Section 000-010-015.
- 1.05 If equipment design and/or manufacturing problems should occur, refer to Section SW 010-522-906 for procedures on filing an Engineering complaint.

2. ORDERING PROCEDURE

- 2.01 The FD-2240A 6.3MB Optical Line Terminating Multiplexer (6.3MB O-LTM) Spare Units and Components may be ordered via the Southwestern Inventory Management System (SWIMS).
- 2.02 To order additional copies of this practice, use NECA 365-407-826SW as the section number.

3. REPAIR/RETURN

- 3.01 Malfunctioning units may be returned to NEC America, Inc., for repair.

Attachment: NEC America, Inc.
FD-2240A 6.3MB Optical Line
Terminating Multiplexer
Spare Units and Components

PROPRIETARY
Not for use or disclosure outside Southwestern Bell
Telephone Company except under written agreement.

NECA 365-407-503
Issue 2, December 1986

FD-2240A 6.3MB OPTICAL LINE TERMINATING MULTIPLEXER
SPARE UNITS AND COMPONENTS

NEC America, Inc. 14040 Park Center Road
Transmission Division Herndon, Virginia 22071
Phone No: (703) 834-4000
Fax No: (703) 481-6904
Telex No: 899498
TWX No: 710-831-0639
Easylink No: 62939917

NEC PRACTICE NECA 365-407-503
Issue 2, December 1986

FD-2240A
6.3MB OPTICAL LINE TERMINATING MULTIPLEXER
SPARE UNITS AND COMPONENTS

CONTENTS	Page
1 INTRODUCTION.....	1
2. SPARE UNITS AND COMPONENTS.....	1

TABLE

Table	Title	Page
2-1	Recommended Spare Unit and Components.....	2

1. INTRODUCTION

1.01 This practice provides a listing of spare units and components necessary to support FD-2240A.

1.02 Issue 2 of this practice supersedes Issue 1 of NECA 365-407-503 The practice corrects errors and omissions in the superseded document.

1.03 Whenever this practice is reissued, the reason for reissue will be listed in this paragraph.

2. SPARE UNITS AND COMPONENTS

2.01 Table 2-1 lists recommended spare units and components.

Copyright 1986 by NEC America, Inc. All rights reserved.
This document is not an offer to sell. The information
contained in this document is subject to change without notice.

Recommended Spare Units and Components

UNIT/COMPONENT	SPARE RATIO REQUIRED	MINIMUM QUANTITY	CODE NUMBER
ALM	1 : 1	1	X0314A, A1, AA
6M OPT INF	1 : 4	1	X0307B, C, C1
DS2 INF	1 : 4	1	X0308A, A1
MUX	1 : 4	1	X0300
DMUX	1 : 4	1	X0301A, A1
CTRL	1 : 2	1	X0316A, A1
	1 : 2	1	X7387A, B
SV	1 : 1	1	X0315A
PWR	1 : 2	1	X0319A (DC)
	1 : 1	1	X1914A (AC)
MP10 FUSE (1A)	-	2/shelf	A32-9F8779-03