

**CALCULAGRAPHS**  
**MODELS 6 AND 30 AND KS-7769 (MODEL 33)**  
**OPERATING METHODS**

**1. GENERAL**

**1.001** This addendum supplements Section 030-100-301, Issue 1. Place this pink sheet ahead of Page 1 of the section.

**1.002** This addendum is issued to change note following paragraph 3.29. This addendum does not affect the Equipment Test List.

**2. CHANGES TO SECTION**

**2.001** On Page 5, change note following paragraph 3.29 to read as follows:

*Note:* To operate the motor-alternator without load, the "A" relay in the 24-volt supply leads to the motor must be manually blocked non-operated.

**NOTICE**

Not for use or disclosure outside the  
Bell System except under written agreement