• App 1 069-000-OOOPT U Numerical Index

CABLING, WIRING, SKINNING, CONNECTING Add 069-110-811LL A Wiring and Cabling — Reinforcement of Cable Forms

069-1

PACIFIC TEL NUMERICAL INDEX — DIVISION 063 MISCELLANEOUS METHODS

1. GENERAL		Section Number	Issue	0.11	
1.01	This appendix supplements the AT&T Numerical Index and lists:		Number	ISSUE	Subject
_	All Pacific Co. issued practices.	• App 1	069-120-811PT	Α	Bradley Insulation Strippers — Description and Use
_	All valid Pacific Co. issued Flashes affecting this division.		069-120-901PT	В	Party Line Grouping Block — Connections
_	Long Lines practices Standard for use in the Pacific Co.		069-130-811		NOT STANDARD
_	AT&T practices NOT STANDARD for Pacific Co. use. (See AT&T index for issue number.)		069-130-811PT	В	Method of Connecting Wires to Split Terminals
1.02	A bullet indicates an item that has been added or changed since the previous issue of the index.		069-199-900PT	Α	Inspection — Locating and Clearing AC Unbalances
1.03 item. C	A square indicates a canceled item. Information relating to the cancellation, if necessary, will be shown in a note following the canceled items and related notes will be deleted upon reissue of the in-	069-3	CLEANING, TREATING, AND RECONDITIONING OF APPARATUS AND EQUIPMENT — GENERAL		
dex.		App 1	069-310-801 P	Т А	Salvaging and Disposing of Precious Metal Contact Material
1.04	A crescent (C) indicates an associated Flash(es) exists against the section.		069-343-900PT	. A	Terminal Clamping Strip — PTS-73
1.05 assigni	A solid diamond indicates a number assigned for a future practice. Practices issued as a preliminary under a future BSP number ment are not recognized as official BSP publications.	App 1	069-360-801 P	т а	14-Type Register — CMC 8080/8081 Meter Klean — Register Cleaner
1.0®	An asterisk (*) indicates a registered trademark,		069-392-901 P	ΓА	Reconditioning Central Office and PBX Equipment Damaged by Water
1.07	A club indicates a section that refers to a manufacturer's manual providing a number for filling purposes, and instructions for		069-393-901 P	ΓА	Distributing Frames — Cleaning
orderin	g the manual (if required).	069-5	CLEANING, TREATING, AND RECONDITIONING OF APPARATUS AND EQUIPMENT — STEP-BY-STEP OFFICES		
	Section				
069-0	Number issue Subject INDEXES, EQUIPMENT TEST LISTS, AND GENERAL	App 1	069-501-801P	ΓА	197- and 198-Type Switches and Associ- *ated Banks, Commutators, and Wipers — Cleaning Requirements and Pro-
	APPARATUS INFORMATION		cedures — Abrasive Cleaning Using CMC Microscrub		