



## OBSERVATIONS AND TESTS TO BE MADE BEFORE CLIMBING OR WORKING AT JOINT USE POLES

### 1. GENERAL

**1.001** This addendum supplements Section 620-105-010, Issue 4.

**1.002** This addendum is issued to provide an alternate method of using the B Shunting Capacitor with B Voltage Testers which have tape reinforced ferrules.

### 5. VOLTAGE TESTS AND SAFEGUARDS — POLES WITH STREETLIGHT FIXTURES

Add the following to Paragraph 5.02(h)(2)

If the metal cap or ferrule of the B Voltage Tester has been tape reinforced, attach the large clip of the temporary bond to the metal terminal of the capacitor; attach the small clip to the toothed metal disk of the B Voltage Tester as shown below.

