

practice index number 14

June
1984

This Practice Index Number 14, dated June 1984, lists those Practices included in a complete set of current Tellabs technical literature. It replaces Practice Index Number 13, dated March 1983, which should be removed from your Tellabs Practice Catalog binder and discarded. **Practice Index Number 14 will be valid until January 1985.** File Practice Index Number 14 at the front of your three-volume Tellabs Practice Catalog set.

This Index and your Tellabs Practice Catalog are arranged numerically (by product model number) into nine sections. Within each section, numerical product-model-number order is followed. A star (★) in front of an entry in Index Number 14 indicates a Practice not listed in previous indexes.

Practice section numbers and dates listed in **Practice Index Number 14** reflect the most current literature available on the most current issue of each respective product (Section num-

product

section 1

Type 10, Type 10 Universal & Type 10 Connectorized Universal Mounting Shelves.....	practice section 8210XX, September 1979
★ 1911 and 1912 Apparatus Cases	practice section 821911/831912, February 1983
★ 1913 Apparatus Case	practice section 841913, April 1983
★ 1914/1914P/1914PR Apparatus Case	practice section 831914/831914P/831914PR, March 1983
★ 1922 Apparatus Case	practice section 821922, March 1984

section 2

24X Mounting Assembly	practice section 8224X, October 1981
242 2Wire Distributive Data Bridge (DDB) System.....	practice section 82242, January 1981
243 Low Speed Data Signaling System, 4311 Data Conversion, and 4312 Loop Interface modules.....	practice section 82243/824311/814312, June 1981
243 Low Speed Data Signaling System and 4313 Alarm Station Interface Module.....	practice section 82243/824313, June 1981
244 4Wire Distributive Data Bridge (DDB) System	practice section 82244, December 1980
246 Resistive Data Bridge (RDB) System	practice section 81246, November 1981
248RF Mounting Assembly	practice section 81248RF, October 1977
251 24-Channel Digital Echo Canceller System.....	practice section 81251, November 1982
★ 260 Signaling and Terminating System	practice section 83260, April 1983
261 Signaling and Terminating System.....	practice section 82261, April 1978
★ 263A Data Station Termination Assembly.....	practice section 85263A, May 1984
263B Data Station Termination Assembly.....	practice section 82263B, May 1979
★ 263DA/263DB Data Station Termination (DST) Systems	practice section 81263DA/81263DB, May 1983
★ 263DC Data Station Termination System	practice section 81263DC-1/81263DC-2/81263DC-3, May 1984
265A Voice Signaling System.....	practice section 82265A, June 1979
267S Signaling and Terminating Assembly	practice section 81267S, August 1981
269S Signaling and Terminating System.....	practice section 82269S, March 1980
★ 281A and 281B Teleconferencing System Description	practice section 81281A/B-1, January 1984
291 Conference/Alerting System.....	practice section 82291, July 1981
291R Conference/Alerting System (FCC Registration No. BPX826-68172-KF-N)	practice section 81291R, November 1981

continued

bers and dates are found in the upper righthand corner of the front page of each Practice. The Practice section number corresponds directly to the Issue number of the product covered in that Practice. The Issue level of the product is defined by the second digit of that number, i.e., an "824411A" is an Issue 2 model 4411A.) Practices covering earlier issues of products or covering products that have been manufactured discontinued or reduced to an additions-and-maintenance-only order status are not listed. You'll want to retain Practices covering these products if you currently use them. Otherwise, all other previous revisions of Practices (those with an earlier date code than listed) should be discarded.

Practices on products of special or limited interest are not included in the general Practice Catalog. Use the "Ordering Sheet for Limited Distribution Practices" to obtain practices not included in the general Catalog.

most current literature available



section 2

292R Conference/Alerting System Description (FCC Registration No. PBX826-68172-KF-N).....	practice section 81292R-1, September 1982
292R Conference/Alerting System Installation (FCC Registration No. BPX826-68172-KF-N)	practice section 81292R-2, September 1982
293 One-Way Alerting System Description	practice section 81293-1, June 1982
293 One-Way Alerting System Installation.....	practice section 81293-2, June 1982
294 Community Alerting System Description (FCC Registration No. BPX826-69545-OT-N).....	practice section 81294-1, December 1982
294 Community Alerting System Installation (FCC Registration No. BPX826-69545-OT-N).....	practice section 81294-2, December 1982

section 3

3228 Data Set Transmit/Receive Module.....	practice section 823228, November 1982
★ 345 Status/Control Concentrator System Description	practice section 81345-1, June 1983

section 4

4001 and 4002 Line Amplifiers.....	practice section 824001/824002, August 1981
4001A Line Amplifier.....	practice section 824001A, July 1982
4001C and 4002C Prescription Line Amplifiers	practice section 824001C/824002C, August 1982
4001E and 4002E Prescription Line Amplifiers.....	practice section 814001E/814002E, March 1981
4003A Line Amplifier with Loopback	practice section 824003A, January 1983
4003C Line Amplifier with Loopback.....	practice section 814003C, November 1980
4006 Compression Amplifier.....	practice section 814006, February 1977
4008 Program Amplifier.....	practice section 834008, September 1979
4012 Program Distribution Amplifier	practice section 814012, July 1977
4018 and 4018A Program Distribution Amplifiers	practice section 814018/814018A, September 1977
4024 2Wire to 4Wire Repeater (24V4) w/Addendum.....	practice section 834024, April 1982
4024A 2Wire/4Wire Repeater Module.....	practice section 814024A, January 1982
4041 Amplitude/Delay Equalizer.....	practice section 824041, May 1982
4101 Echo Suppressor	practice section 814101, May 1976
4201 Terminating Set	practice section 824201/824203, July 1980
4203 Terminating Set w/A&B-lead inductor.....	practice section 824201/824203, July 1980
4212A Data Station Termination (4w line/2w sta.)	practice section 814212A, April 1981
423X Precision Balance Networks.....	practice section 81423X, October 1979
4401 Pad module, 4wire	practice section 814401/2/3/4, September 1976
4402 Pads and Transformer, Facility.....	practice section 814401/2/3/4, September 1976
4403 Pads and Transformer, Office.....	practice section 814401/2/3/4, September 1976
4404 Pads and Transformer, Station.....	practice section 814401/2/3/4, September 1976
4404S Pad/Transformer Module with Sealing Current	practice section 814404S, July 1981
4405 4Wire Station Termination Module.....	practice section 814405, November 1977
★ 4406 KTU 4Wire Station Termination Module.....	practice section 824406, September 1982
4411 Pad/Transformer/Loopback Module	practice section 814411, December 1979
4411A Pad/Transformer/Tone Loopback Module.....	practice section 824411A, August 1978
4412A Data Station Termination	practice section 824412A, June 1981
4412AS Data Station Termination with Sealing Current.....	practice section 814412AS, August 1981
4412B Data Station Termination Module	practice section 814412B, April 1980
4412C Data Station Termination w/tone Loopback.....	practice section 814412C, April 1980
4412D Data Station Termination w/timeout Loopback.....	practice section 814412D, April 1980
4412U Data Station Termination (DST) Module	practice section 814412U, January 1983
4413 Data Station Termination, Voice Alternate	practice section 814413, July 1977
4414 Alternate Voice/Data (AVD) Amplifier.....	practice section 814414, February 1978
★ 4416 and 4416A Data Station Termination Modules	practice section 814416/814416A, March 1984
★ 4417 and 4417A Data Station Termination Modules	practice section 814417/814417A, March 1984
★ 4418 and 4418A Data Station Termination Modules.....	practice section 814418/814418A, March 1984
4421 Repeat Coil, Single.....	practice section 814421/2/3, December 1979
4422 Repeat Coil, Dual	practice section 814421/2/3, December 1979
4423 Repeat Coil, Dual Protected.....	practice section 814421/2/3, December 1979
4424 and 4425 Wideband Repeat Coil Module	practice section 824424/824425, August 1978
4425 Wideband Repeat Coil Module.....	practice section 824424/824425, August 1978
4444 Active Bridge, 4Wire 4Way.....	practice section 814444/814446, May 1979
4445 Dual 4Wire 5Way Active Data Bridge	practice section 824445/824449, November 1978

continued

section 4

4445A Dual 5Way Balanced Active Data Bridge	practice section 814445A, February 1982
4446 Active Bridge, 4Wire 6Way.....	practice section 814444/814446, May 1979
4449 Dual 4Wire 9Way Active Data Bridge	practice section 824445/824449, November 1978
4459 DDB Loopback/Facility Test Module.....	practice section 814459, April 1981
4502 Equalized Line Amplifier.....	practice section 814502, November 1979
4744 4Wire Line Amplifier.....	practice section 824744, September 1979
4901 4Wire Pad: 4902 4Wire Pad/ Transformer Modules	practice section 814901/814902/814910, March 1978
4910 4Wire Bypass Module.....	practice section 814901/814902/814910, March 1978
4942 Terminating Set.....	practice section 814942, August 1977
4944 Dual Line Amplifier.....	practice section 814944, March 1979

section 6

6001 and 6002 DX1/DX2 Signaling Modules.....	practice section 846001/846002, June 1980
6003 and 6004 2Wire Auto Ringdown Module	practice section 826003/826004, June 1976
6006 Signaling Converter, 20Hz-E&M, SG-20Hz, or SG-E&M	practice section 816006, April 1978
6041 Network Terminating Module	practice section 816041, December 1981
6042 Network Terminating Module	practice section 826042, September 1981
★ 6042A 4W-2W DX Network Terminating Module with Loopback.....	practice section 826042A, February 1984
6044 Network Terminating Module	practice section 826044, August 1981
★ 6044A 4W-4W DX Network Terminating Module with Loopback.....	practice section 826044A, December 1983
★ 6047 and 6047A 4W-to-4W SF-to-E&M Network Terminating Modules.....	practice section 816047/826047A, October 1983
★ 6048 and 6048A 4W-2W or 4W-4W SF-to-E&M Network Terminating Modules with Gain.....	practice section 816048/826048A, May 1983
6101 SF Transceiver.....	practice section 816101, September 1976
6102 E&M Signaling Converter	practice section 836102, January 1981
6103 Foreign Exchange, Station (FXS) Signaling Converter.....	practice section 816103, April 1978
6104 Foreign Exchange, Office (FXO) Signaling Converter.....	practice section 826104, April 1981
6105 ARD (Ringdown) Signaling Converter.....	practice section 836105, June 1981
6106 Data ARD Signaling Converter	practice section 816106, June 1978
★ 6122 and 6122A 2W E&M SF Signaling Sets.....	practice section 816122/826122A, August 1983
★ 6123 and 6123A 2W FXS SF Signaling Sets with Gain.....	practice section 816123/816123A, March 1983
★ 6124 and 6124A 2W FXO SF Signaling Sets.....	practice section 816124/816124A, September 1983
6201 Two-Way Loop-to-E&M Converter	practice section 816201, June 1978
6205 AIOD Converter (SX-E&M) Module	practice section 816205, January 1981
6206 AIOD Converter (E&M-SX) Module	practice section 816206, February 1981
6251 SSN Trunk Module	practice section 826251, April 1981
6256 RBR Trunk Module.....	practice section 816256, June 1977
6271 Tie Trunk Answer Supervision Module.....	practice section 816271, July 1982
6461 Common Signaling Module (2W/4W).....	practice section 816461, September 1979
6462 4Wire Common Signaling Module	practice section 816462, April 1980
6920 Echo Suppressor	practice section 826920, June 1978
6920B Transparent Echo Suppressor	practice section 836920B, June 1978
6921A and 6921B Echo Cancellers	practice section 826921A/B, January 1983
★ 6921G and 6921H Long-End-Path Echo Cancellers.....	practice section 826921G/826921H, September 1983
6922 2Wire E&M SF Signaling Set.....	practice section 826922, August 1979
6923 2Wire Foreign Exchange, Station (FXS) SF Signaling Set	practice section 826923, September 1979
6924 2Wire Foreign Exchange, Office (FXO) SF Signaling Set	practice section 826924, February 1980
6925 2Wire Ringdown SF Signaling Set	practice section 826925, May 1980
6927 and 6927A 2Wire Universal SF Signaling Set Modules with Gain	practice section 816927/816927A, April 1981
6942 4Wire E&M SF Signaling Set.....	practice section 816942, August 1979
6943 4Wire Foreign Exchange, Station (FXS) SF Signaling Set.....	practice section 816943, January 1980
6944 4Wire Foreign Exchange, Office (FXO) SF Signaling Set.....	practice section 816944, May 1980
6945 4Wire Ringdown SF Signaling Set	practice section 816945, May 1980
6947 and 6947A 4Wire Universal SF Signaling Set Modules with Gain	practice section 816947/816947A, August 1981

continued

section 6

- ★ 6962 and 6962A 4W E&M SF Signaling Sets with Gain..... practice section 836962/826962A, March 1983
- 6971 Common Interface Module (2W/4W) practice section 816971, April 1980
- 6972 4Wire Common Interface Module practice section 816972, April 1980
- 6991 2Wire-to-4Wire E&M OUTWATS Adapter..... practice section 816991, August 1981

section 7

- ★ 7001 Dial Long Line Module and 7001A Network Terminating Dial Long Line Module (LSO) practice section 837001/817001A, December 1982
- ★ 7002 Dial Long Line Module and 7002A Network Terminating Dial Long Line Module (LS/GS) practice section 827002/817002A, June 1983
- 7011 and 7011A Off-Premises-Extension (OPX) Range Extenders practice section 827011/817011A, May 1982
- 7201 2Wire Switched-Gain Repeater practice section 847201, November 1981
- 7206 2W Switched-Gain Compression Amplifier practice section 817206, April 1982
- 7206A and 7206B 2W Switched-Gain Compression Amplifier Modules practice section 817206A/817206B, April 1982
- 7213 2Wire Hybrid Repeater with DLL practice section 817213, September 1982
- 7501 Dial Long Line Module practice section 837501, November 1983
- ★ 7503 Dial Long Line Module (high density) practice section 847503, July 1983
- 7505 Test-Through Dial Long Line Module practice section 817505, May 1980
- 7701 2Wire Switched-Gain Repeater (high density) practice section 817701, April 1980

section 8

- 8001 24/48Vdc Power Supply..... practice section 838001, March 1979
- 8101 Ringing Generator, 30Hz practice section 818101, August 1975
- 8102 Ringing Generator, 20Hz practice section 818102, March 1977
- 8205 Dual Battery Filter and Fuse Distribution Panel practice section 818205, January 1983
- 8211 Fuse Panel practice section 818211/818212, May 1977
- 8271 Ballast Lamp Panel practice section 818271/818272, June 1978
- 8272 Ballast Lamp Panel practice section 818271/818272, June 1978

section 9

- 9001 and 9002 Relay Modules practice section 819001/2, August 1975
- 9011 Pulse/Trunk Link Repeater and Dual Pulse Corrector..... practice section 819011, September 1976
- 9021 Fuse Module..... practice section 819021, February 1978
- 9024 Sealing Current Module practice section 819024, February 1978
- 9026 Jackfield Module practice section 819026, February 1978
- 9101 Automatic Exclusion Circuit practice section 819101, September 1979
- 9103 Subscriber Transfer Circuit practice section 819103, April 1978
- 9104 INWATS Line Relay module practice section 819104, January 1979
- 9131 Universal Timer practice section 819131, September 1979
- 9608 Program Amplifier and
9608A Program Distribution Amplifier practice section 819608/819608A, January 1981
- 9662 4Wire E&M SF Signaling Set with Gain..... practice section 829662, September 1981
- 9781 Precision Balance Network practice section 819781, August 1977
- 9791 Loudspeaker practice section 819791, November 1978
- 9807 Card Extender practice section 819807, February 1979
- 9901 Pulse Corrector, 8-14pps Input practice section 819901/2, September 1976
- 9903 Ringing Interrupter practice section 829903, September 1976
- 993X Precision Balance Networks practice section 83993X, April 1982
- 9961A FXS Signaling Converter Subassembly..... practice section 819961A, October 1978
- 9961B FXO Signaling Converter Subassembly practice section 819961B, October 1978
- 9961C Ringdown Signaling Converter Subassembly practice section 829961C, March 1981
- 9961D DX Signaling Converter Subassembly practice section 819961D, April 1980
- ★ 9961E Pulse Link Repeater Subassembly practice section 819961E, January 1983